Oil Field Environmental Incident Summary

Responsible Party: Liberty Resources Management Company, LLC

Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Name: LASSEY-MYERS A 1

Field Name: GLASS BLUFF Well File #: 11177

Date Incident: 10/12/2014 Time Incident: 10:00 Facility ID Number:

County: MCKENZIE Twp: 152 Rng: 103 Sec: 33 Qtr: NE NE

Location Description: Lassey-Myers A1 Injection Facility. Spill was contained inside a lined dike on

location.

Submitted By: Tappan Souther Received By:

Contact Person: Tappan Souther

1200 17TH STREET, SUITE 2050

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2640 Feet **Distance Nearest Water Well:** 2640 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 100 Barrels 100 Barrels 100 barrels

Other

Description of Other Released Contaminant:

Produced salt water used as injection fluid in waterflood.

Inspected: Written Report Received: 12/21/2016 Clean Up Concluded: 10/14/2014

Risk Evaluation:

None - Injection pump was shut off and all 100 bbls were recovered and taken to the Monson facility.

Page 1 of 2

Areal Extent:

All 100 bbls were contained in a lined dike that surrounds the injection pump.

Potential Environmental Impacts:

None - Injection pump was shut off and all 100 bbls were recovered and taken to the Monson facility.

Action Taken or Planned:

Injection pump was shut off and all 100 bbls were recovered via a hydraulic vacuum truck and taken to the Monson facility. Cracked nipple will be replaced as well as reviewing the failure with the vendor/manufacture of the pump to prevent future incidents. Continue to maintain integrity of the lined dike system on location. Pumper (Tom Ruland) called and notified the NDIC of spill.

Wastes Disposal Location: The 100 bbls of recoverd fluid was taken to the nearby Monson facility for disposal.

Agencies Involved:

Updates

Date: 10/14/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.